

I hereby authorize the repair work listed hereon, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling charge (including reassembling) will be made.

X

CUSTOMER SIGNATURE

**ELROY'S SERVICE
CENTER
FRONTIER FORD, INC.**
WEST HIGHWAY 44
PLATTE, SD 57369
PHONE (605) 337-3152
1-800-491-3152

NAME, ADDRESS, CITY, STATE, ZIP CODE CARROLL POPPEN 5753 LONGBOAT RD ROCHESTER MN 55901 HOME PHONE 1-507-288-1895 WORK PHONE		VIN # 1FTNX21F51EA79993	YEAR/MAKE 01 FORD	MILEAGE 26612	ENGINE NUMBER 7.3L POWER STROKE	PURCHASE ORDER	
		LICENSE NUMBER EMN 713			AD CODE	WIR/F	
		TRANS TYPE F40D	MODEL/COLOR F-250 4WD		PC R WRITTEN BY		
VEHICLE PROBLEM STATEMENTS CHECK DAMAGE FROM ACCIDENTAL RIFLE DISCHARGE =====		FLAT RATE	MECH. NO.	LABOR OPERATIONS		PRICE	
AMERICAN FAMILY INSURANCE CLAIM #351-1357567				INSPECT FOR DAMAGE FROM ACCIDENTAL RIFLE DISCHARGE. R&R		0	
				EXHAUST TURBO PIPE & CHECK FOR COOLANT LEAK. (HOLE IN ENGINE CYLINDER BLOCK) R&R ENGINE ASS		0	
				& INSTALL NEW ENGINE. TRANSFER PARTS. FILL WITH OIL & COOLANT		0	
		2		CHECK FLUID LEVELS & ROAD TEST		980.00	
				=====		0	
RECOMMENDED SERVICE DAMAGE TO EXHAUST-TURBO & ENGINE BLOCK REPAIR FIREWALL DAMAGE INSTALL ENGINE ASSY & TRANSFER PARTS		2		REPAIR DAMAGE TO FIREWALL		49.00	

ESTIMATE OF REPAIRS: Includes all parts, labor, handling and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

TOTAL LABOR

1029.00

Parts installed are not warranted beyond that given by respective manufacturers. No other warranties are made except as listed on this invoice.

C	QTY.	PART NUMBER	PART DESCRIPTION	AMOUNT	C	QTY.	PART NUMBER	PART DESCRIPTION	AMOUNT
N	1	XC3Z-6006-ANM	FORD ENGINE ASSY	6973.33	N	1	FROST FREE	ANTIFREEZE	22.10
N	1	CORE	DAMAGE CHARGE	3000.00	N	2	FW16	COOLING SYSTEM COND.	11.96
N	1	F8TZ-6K854-AA	HOUSING	70.93	N	15	15 QTS.	MOTORCRAFT 15W40 OIL	30.00
N	1	F81Z-6K854-EA	EXHAUST TURBO TUBE	32.07	N	2	10-345	NUT	1.16
N	1	F81Z-9C387-BA	LINE SEAL KIT	9.51	N	4	ATF	AUTO TRANS FLUID	9.20
N	1	F81Z-6W653-BA	TURBO SEAL KIT	81.98	N	1		FREIGHT	100.00
N	1	F4TZ-8507-A	WATER PUMP SEAL KIT	21.14	N	1	TH	THANKS FOR YOUR	0
N	1	F8TZ-8575-AA	THERMOSTAT	35.41	N	1	BH	BUSINESS	0
N	2	1821840C1	BOLT	10.28	N	1	WA	WE APPRECIATE IT.	0
N	2	40054R1	NUT	3.28					
N	6	40050R1	NUT	18.48					
N	6	1822895-C1	BOLT	46.80					
N	2	F4TZ-6K854-C	SEAL	15.24					
N	2	24815	O-RING	3.88					
N	1	24528	O-RING	.78					

C=CODE N=NEW R=REBUILT U=USED C=REFUNDABLE CORE DEPOSIT

I acknowledge notice and oral approval of an increase in the original estimated price

SIGNATURE OR INITIALS

PHONE AUTHORIZATION

DATE

EMPLOYEE NO.

1:DAN BETHKE/EXT-63550 2:CARROLL

1:11/28/01 2:11/28/01

1 / 1

TIME 12:55P

12:56P

AMOUNT OF NEW ESTIMATE

1: 12085.07

2: 12085.07

1-800-374-1111

1-507-288-1895

DONE ☐

CALLED ☐

SAVE YES ☐

PARTS: NO ☒

SUBLET

0

SUPPLIES

15.00

DATE

12/11/01

R.O. NUMBER

28871

LABOR

1029.00

PARTS

10497.53

TOTAL TAX

692.49

TOTAL

12234.02

PS04777