

DEAR SIR.

THIS RIFLE REM. # 42083 S.NO.
MODEL 600 SOMETIMES HANG
FIRE AND ONE TIME
DISCHARGED WHEN THE
BOAT WAS PUSHED IN
TO RELOAD THIS IS VERY
DANGEROUS WHEN THIS
RIFLE IS REPAIRED SEND
IT BACK TO ME AT
MY HOME

P.S. THERE'S ONE SCREW OUT
ON THE OPEN SIGHT.

HOMER PHILLIPS

13974 NWY 902

BEAR CREEK N.C.

27207

AERIA CODE 919 837 5913

PHONE