

December 9, 1994

ROBERT M. PIECHOWSKI
R.R. 4 BOX 262
EXCELSIOR SPRINGS, MO 64024-9109
816 637-1446

REMINGTON ARMS CO
ARMS SERVICE DIVISION
14 HOEFLER AVE.
ILION, NY 13357

REFERENCE: REMINGTON MODEL 721, CAL 270, SN 168685

THIS RIFLE RECENTLY ACCIDENTLY DISCHARGED WHEN CLOSING THE BOLT.
NO ONE WAS INJURED, BUT I CERTAINLY WAS SHOCKED.

I TOOK THE RIFLE TO J R GUNS IN KEARNEY, MO. THE GUNSMITH HAD ME SIGN
A RELEASE SAYING THAT MY RIFLE WAS UNSAFE AND THAT I SHOULD CONTACT
REMINGTON BECAUSE THESE GUNS WERE BEING RECALLED ON A "AS NEEDED
BASIS" FOR REPLACEMENT. HE WOULD NOT ORDER THE TRIGGER ASSEMBLY,
NOR DID HE EVEN SUGGEST REPAIRING IT. HE SAID I SHOULD CONTACT
REMINGTON FOR A REPLACEMENT RIFLE.

I HAVE CONTACTED YOUR DEPARTMENT AND DENNIS GAVE ME THE
INSTRUCTIONS TO RETURN THE RIFLE FOR INSPECTION, REPAIR, OR
REPLACEMENT.

PLEASE INSPECT MY RIFLE AND LET ME KNOW THE STATUS.

THANK YOU.



ROBERT M. (BOB) PIECHOWSKI