



THE PALMOUR GROUP

November 10, 1993

fill
Remington Arms Company, Inc.
Product Service
14 Hoefler Avenue
Ilion N. Y. 13357

HAROLD H. PALMOUR
DORTHA M. PALMOUR



Attention Mr. Sonita

Dear Mr. Sonita,

Re my telephone conversation of November 9, 1993, concerning my Model 700 rifle.

The problem is it will fire when chambering a round or when a safety is pushed forward.

I shipped it to your attention by U.P.S. today and you should receive it Friday, November 12, 1993, or Monday, November 15.

Please advise what caused the problem and what you can do to fix it. We are very fortunate no one was injured because of this malfunction.

Sincerely,

Harold Palmour

1 Copy - File