

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER R 98-17214

INITIAL CUSTOMER ORDER NO

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

08/26/98

08/27/98

KQ 5-96

D6239311

700 308

POL/DM

ACCESSORIES

W/STUDS

FROM

SHIP TO

PEORIA POLICE DEPT/TNG UNIT
600 SW ADAMS ST

PEORIA POLICE DEPT/TNG UNIT
600 SW ADAMS ST
ATTN SGT J W ADAMS
PEORIA IL

PEORIA

IL 61602

61602

CUST NO: 154946 IL-ION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

2074501

WRITE ☐

PROM DATE

ESTIMATED

VIA

9-2-98

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

*Function Bolt Group
Barrel is not seated properly*

Upon receipt we noted that the trigger would not retract & must use thumb on the back of trigger housing to move. Rifle has not been properly maintained.

COMMENTS

*Repair the trigger group
clean & check other bedding
at no charge to customer
Good work.*

RBS

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD5925 REV 7-97

PS04916