



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00060906	Description/Serial Number D6272160	Repairman - Herb Brown Date Received - 1/31/2003
Account # - R-	Model 700 Center Fire Caliber: 308 PSS DM	Estimate Date - Current Date - 2/6/2003
Customer PULASKI CO SHERIFFS OFFICE ATTN SGT SIMON HAYNES 2900 S WOODROW LITTLE ROCK, AR 72204 US		Return To PULASKI CO SHERIFFS OFFICE ATTN SGT SIMON HAYNES 2900 S WOODROW LITTLE ROCK, AR 72204 US
Phone (H) (501)-340-6966		Fax
Phone (W)		Email

Reported		Problems	Found
M992	FIRES WHEN SAFE RELEASED	M123 M178	FORWARD TO PRODUCT SERVICE F TRIG ADJ SCREWS RESET, CANNOT

Material #		MaterialDesc	Repair	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
Part Total:				1	0	0	
Service							
4000294		GR-CHECK TPA		1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				2	2	0	

ProblemNotes Trigger adjusting screws re-set out side factory. Inside trigger housing dirty .

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date