



Ronald O'Quinn
250 Herman Rd.
Reidsville, NC 27320-8929

Remington

52886

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700		Serial Number: B 6281549	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: R.W. O'Quinn		Date of Purchase: 1983	
Address (no PO Boxes): 250 Herman Rd.			
City: Reidsville		State: NC.	Zip: 27320
Phone (Daytime): (336) 342-6543		Fax:	
E-mail Address:			
<input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem: Sometimes the Trigger is hard to pull — when you fire this gun and flip another round in chamber the gun fires without pulling the Trigger (fires on its own) (REAL dangerous)			
Ammunition Information:			
Manufacturer: Remington		Type: 30-06 150 gr.	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: WD 40			
How often do you clean the bore? (Months or Number of rounds)			
How often do you clean the action? (Months or Number of rounds)			
How often do you clean the trigger assembly? (Months or Number of rounds)			
Brand of lubricant used:			
How often do you lubricate the bore? (Months or Number of rounds)			
How often do you lubricate the action? (Months or Number of rounds)			
How often do you lubricate the trigger assembly? (Months or Number of rounds)			
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			

Fires ITS

Clean often
Have not
used this gun
this much
(AFRAID TO
USE)