

Jerry D. Rodgers
Rt # 2 Box 531-B
La Fayette, Ga. 30728

Dear Sir:

I am returning this rifle for repair.

Serial # C6521887.

Problem #1. Rifle doesn't shoot a tight group. (See enclosed target). Any good rifle should shoot a $1\frac{1}{2}$ inch group at 100 yds. I own three other rifles, all Remingtons, they shoot near a inch at 100 yds. This one should to. —

Problem #2. Firing Pin falls when you close the bolt. It sometimes falls when you push the safety off.

Also would you please set trigger at four pound pull.

I purchased the rifle on 7-6-91 and have fired it approx. 50 times. I tried several different loads, including factory rounds. It never group well with any of them. I was shooting groups to send to you when the firing pin started falling. I stopped shooting!

Thank-you
Jerry D. Rodgers



ase - Remington
 powder - IMP 4350
 undercharge - 81 grains
 Bullet - 150 grain Speer
 Primer CCI 250
 Scope - 2.5x8 Leupold VIII

Five shot group from
 benchrest with sandbags.
 I let barrel cool between
 shots. This is an average
 group that the rifle will
 do. Heavier bullets do
 somewhat better, but not
 much. Any good rifle
 should shoot around $1\frac{1}{2}$ inches.
 Please fix it!