


William P. Reisinger
308 B E. Lancaster St.
Rect Lion, Pa. 17356



Remington Arms Co. Inc.
P.O. Box 179
Ilion, N.Y. 13357

Remington Arms Co.



I am the owner of a Model 700 7MM magnum. A year ago, my rifle was sent to your company on recall for a trigger mechanism failure which could cause the gun to fire on safety position. Before recall, my gun was firing true. However, shooting prior to the upcoming 1989 Deer season, my rifle misfired on shifting safety switch from safety to fire without pulling the trigger. This happened only on one occasion but because of it, I hunted the "89" season without using the safety. I have not fired the rifle since.

I was wondering if your company has had any other similar reports.

I would appreciate hearing from you.

I will probably be taking my rifle
JUL 12 1980 a nearby gunshop.

RECEIVED

Sportingly William P. Remington