

Remington.**REMINGTON ARMS COMPANY, Inc.**SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS
ILION, NEW YORK 13357

PAGE 1

DATE: 10/28/91

PARTS: (315) 895-7493; REPAIRS: (315) 895-7791

SOLD TO

SHIPPED TO

REPAIR ORDER NO.

REPAIR ORDER NO.: 91-21198

91-21198

MOUNTAIN & STREAM SPORTS SHOP

P O BOX 285

NETTIE

WY 26681

CUSTOMER NUMBER: 51410

MOUNTAIN & STREAM SPORTS SHOP

P O BOX 285

NETTIE

26681

WE ACKNOWLEDGE RECEIPT OF THE ITEM(S) DESCRIBED BELOW.

THE NECESSARY CORRECTIONS ARE BEING PERFORMED WITHOUT CHARGE AND PREPAID SHIPMENT WILL BE MADE IN ABOUT 2 WEEKS.

WE KNOW YOU WILL FIND THE REPAIR TO BE COMPLETELY SATISFACTORY AND IF WE CAN HELP YOU IN ANY OTHER WAY, PLEASE LET US KNOW.

7

243

SERIAL NUMBER: 7007000

WY 21000

WY 21000 MANUAL

CUSTOMER REQUEST:

WHEN COCKING BOLT TO INSERT ANOTHER SHELL WENT OFF W/O TOUCHING THE TRIGGER

MAIN FAULT FOUND:

TRIGGER PULL 4 1/4 LBS SEAR LIFT .0095

1 0092400

TRIGGER ASSEMBLY

INSTALL NEW TRIGGER ASSEM AS GOOD WILL RESTORE IF IT WILL
BETTER RESTORE CONFIDENCE IN THE RIFLE
TESTTOTAL REPAIR CHARGE
TAXESINSURANCE
PARCEL POSTTOTAL
CHARGES

NO CHARGE

CUSTOMER COPY

PS05241