

### Repair Order Number



|                                                                                                   |                                                                   |                                                                                                    |
|---------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|
| <b>Repair Order Number</b><br>RE00075741                                                          | <b>Description/Serial Number</b><br>A6765132                      | <b>Repairman -</b> Bruce Travis                                                                    |
| <b>Account # - R-</b>                                                                             | Model 700 Center Fire with 24 inch<br>barrel Caliber: 7MM REM MAG | <b>Date Received -</b> 1/19/2004                                                                   |
|                                                                                                   | CLASSIC                                                           | <b>Estimate Date -</b> 1/16/2004                                                                   |
|                                                                                                   |                                                                   | <b>Current Date -</b> 1/28/2004                                                                    |
| <b>Customer</b><br>KATHI ROFF<br>509 SOUTH HEIGHO AVE<br>P.O. BOX 637<br>NEW MEADOWS. ID 83654 US |                                                                   | <b>Return To</b><br>KATHI ROFF<br>509 SOUTH HEIGHO AVE<br>P.O. BOX 637<br>NEW MEADOWS. ID 83654 US |
| <b>Phone (H)</b> (208)-347-3006                                                                   |                                                                   | <b>Fax</b>                                                                                         |
| <b>Phone (W)</b>                                                                                  |                                                                   | <b>Email</b>                                                                                       |

| Reported |                                              | Problems | Found                        |
|----------|----------------------------------------------|----------|------------------------------|
| M123     | FORWARD TO PRODUCT SERVICE<br>FOR INSPECTION | M123     | FORWARD TO PRODUCT SERVICE F |
| M992     | FIRE WHILE MOVING SAFETY                     |          |                              |

| Material #            |  | MaterialDesc                  | Quantity<br>Needed | Quantity<br>From Inv | Quantity<br>From Kit | Warranty<br>(Y/N) |
|-----------------------|--|-------------------------------|--------------------|----------------------|----------------------|-------------------|
| <b>Part</b>           |  |                               |                    |                      |                      |                   |
| F26345                |  | 700 TRIG ASSB RH              | 1                  | 1                    | 0                    | Y                 |
| <b>Part Total:</b>    |  |                               | 1                  | 1                    | 0                    |                   |
| <b>Service</b>        |  |                               |                    |                      |                      |                   |
| 4000119               |  | GR-TEST                       | 1                  | 1                    | 0                    | Y                 |
| 4000104               |  | ARMS SERV SHIPPING & HANDLING | 0                  | 0                    | 0                    | N                 |
| 4000116               |  | GR-LABOR                      | 20                 | 20                   | 0                    | N                 |
| <b>Service Total:</b> |  |                               | 21                 | 21                   | 0                    |                   |

|                       |                                                                                                                                             |              |             |               |                |
|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------|---------------|----------------|
| <b>ProblemNotes</b>   | mfg date 5/79 could not duplicate the reported concern, but did find sear adjustment screw reset.<br>replace trigger assm for \$20.00 quote |              |             |               |                |
| <b>Repairman</b>      | <b>Proof</b>                                                                                                                                | <b>Clean</b> | <b>Test</b> | <b>Target</b> | <b>Pattern</b> |
| <b>Gallery Tester</b> | <b>Date</b>                                                                                                                                 | <b>Date</b>  | <b>Date</b> | <b>Date</b>   | <b>Date</b>    |