

Date: 10/20/04
By: Bruce Travis G.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: James E. Richards Jr.
R.E. Number: 86686
Reason for inspection: Ries on bolt closing

FIREARM

Manufacturer: Rem. Model: 700
Serial Number: 323520 Date of Manufacture: 1/68
Overall external condition: Good

Barrel condition: okay
Receiver condition: okay
Stock condition: okay
Bolt/firing pin condition: okay
Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: Sticky searcom

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 4.5#

Manual safety: okay

Test firing results (if applicable): _____

DISPOSITION

could not duplicate - Trg. assm. is contaminated
w/ a partially dried + sticky lubrication residue. Replace
TPA + clean action. include bolt lock safety program.
ADDITIONAL COMMENTS for \$20.00 Quote