

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00045198 Account # - R-	Description/Serial Number E6575197 Model 700 Center Fire Caliber: 270 ADL SYNTHETIC	Date Received - 5/2/2002 Estimate Date - 4/22/2002 Current Date - 5/8/2002
Customer SAM RONEY 7130 COTTONWOOD RD DOTHAN, AL 36301 US	Return To SAM RONEY 7130 COTTONWOOD RD DOTHAN, AL 36301 US	
Phone (H) (334)-677-5303 Phone (W)	Fax Email	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO		
M992	FIRE WHEN FINGER TOUCHED SAFETY				

Technician's Comments	
Condition	NICKS ON STK & RUST ? ON BBL. CHIPPED TRIG GUARD.
Problem/Notes	Inside of action and trigger assembly dirty and oily, with sticky residue. Quote customer clean and new trigger assembly at 1/2 normal charges. FLS 4/22/02.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	N
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	N
4000118	GR-CLEAN	1	N
4000119	GR-TEST	1	Y
Service	Total:	2	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

SAM RONEY
7130 COTTONWOOD RD
DOTHAN AL 36301-8100




AL 363 0-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1188 0212



BILLING: PREPAID

INV#: RE00045198

ASC 3.70 J69X/J64X 14.0 01/201