


REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
MILTON NY 13357

10 LBS 1 OF 1

SHIP

TO:

AUGUST SCHROEDER
9452 CRESTFIELD DR
WEST CHESTER OH 45069-4245



OH 451 9-04



UPS GROUND

TRACKING #: 1Z 114 813 03 1187 4514



BILLING: PREPAID

INV#: RE00045020

ASC 3.70 J69K/J64K 14.0 01/2002

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

www.remington.com info@remington.com

Fax

336-548-7801

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00045020 Account # - R-	Description/Serial Number 6342162 Model 700 Center Fire Caliber: 30 06 ADL	Date Received - 4/12/2002 Estimate Date - Current Date - 4/27/2002
Customer AUGUST SCHROEDER 9452 CRESTFIELD DR WEST CHESTER, OH 45069 US	Return To AUGUST SCHROEDER 9452 CRESTFIELD DR WEST CHESTER, OH 45069 US	
Phone (H) (513)-777-1191 Phone (W)	Fax Email	

Problems			
Reported		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE FO
M992	FIRE W/OUT PULLING TRIG.	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Action and trigger assm. covered with dirt, dust and rust. The stock has not been removed so the rifle could be cleaned in years. Clean action and replace trigger assm. at spec. price.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		22	