

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00046035 Account # - R-	Description/Serial Number 6708060 Model 700 Center Fire Caliber: 22250 BDL	Date Received - 5/13/2002 Estimate Date - Current Date - 5/16/2002
Customer SHIRTS N SHOOTERS 26 PLYMOUTH ST SW LE MARS, IA 51031 US	Return To SHIRTS N SHOOTERS 26 PLYMOUTH ST SW LE MARS, IA 51031 US	
Phone (H) (712)-546-9228 Phone (W)	Fax Email	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO		
M238	CLEAN & INSPECT				

Technician's Comments	
ProblemNotes	mfg date 1/74 action and trigger assm dirty - components working sluggish replace trigger assm at special price of \$20.00

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	N
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
Service Total:		21	

REMINGTON ARMS CO INC
800 243-9700
14 MOEFLER AVE
ILLION NY 13357


10 LBS 1 OF 1

COD

SHIP

TO:

SHIRTS N SHOOTERS
26 PLYMOUTH ST SW
LE MARS IA 51031-3525




IA 511 9-31



UPS GROUND

TRACKING #: 1Z 114 813 72 1188 5436



BILLING: PREPAID
COD \$31.80

INV#: RE00046035

ASC 3.70 J69X/J64X 14.0 01/2002