

Bill Speir

102 So. College St.

Greenville, AL 36037

Phone 334-382-9386

Fax 334-382-9386

Home Phone 334-382-3683

August 05, 1999

Remington Arms  
870 Remington Drive  
Madison, NC 27025

Remington Arms,

Last year I traded a Thompson Contender with a friend for a Model Seven .243. I hunted with this weapon for the remainder of the 98'-99' deer season. Recently I used the weapon shooting crows. This is when I noticed the problem. The weapon would discharge if you touched the trigger in the safe position and pushed the safe to fire. I then took the weapon to my local dealer. They in turn sent the weapon to Walker Arms an authorized Remington repair center. They told me they could not warranty the gun without a proof of purchase. So they returned the weapon to Hunter's Hideout of Greenville, AL. They informed me not to use the weapon until I had it repaired. The problem is the fact that I feel this weapon should be repaired cost free due to the nature of the problem. I feel a problem like this one is a defect that could have easily caused a great deal of harm or even death to myself or my son. I have owned Remington firearms literally from the time I could walk and have never had the first complaint on your quality or workmanship. This weapon is in very good shape and has never been tampered with. Please fix or replace this weapon under warranty so that I can still feel that your product is still one of the best firearms on the market today.

Thank You,  
Bill Speir

P.S. The serial number is 7717176 and UPS tracking number is 1ZE13900610007595