

JAN 3 1995

Denn Sims,

I bought this gun used
a short time ago. While working
the bolt several times the
firing pin released when I lowered
the bolt handle. I worked the
bolt about 100 times and it
happened about 4 or 5 times. I
called your service dept. & was
told to send the gun to you.
Also I'm enclosing 5 Fired
Rem. 222 cases with the lot
no. of the ammo. The 5th
round blew the primer as you
can see. I had fired 20
Reloaded rounds (20.0-Rx7 50gr
bullet) before with no problem.
I don't know if there is a
head space problem or what.

Thanks,

Jim Stites

Jim Stites

P.O. Box 341

Concho, Az. 85924

Phone 602 - 337-2087