

Aug. 16, 80

Dear Sir:

I'm writing to you in reference to my 243 ga ~~BD2~~ 700 model enclosed with this letter. I have talked previously to one of your representatives about the problem with the on - off safety. Last year during our hunting season I loaded 4 cartridges in the gun, a single one in the chamber + closed the bolt - with safety ON, + much to my disappointment the gun fired by itself. This caused damage to my camper, mattress, sleeping bags, quilts and also my son's car window, which was parked outside by the end of my camper. Luckily no one was injured from this incident of the gun misfiring with the safety in ON position.

Please check + replace the safety mechanism - as required! - From the factory specifications for this gun.

I can be reached at this address + Phone #

Tommy C. Sitton

Rte 2 Box 325-B

Horse Shoe, N.C. 28742

Area Code 704 - 891 - 2062
(over)

OFFICE COPY

ERN

5 REV. 6/88

If at all possible please repair +
return as soon as possible sending the
statement + charges and I will in turn
send a check for the charges promptly to
you.

Sr. # 7624325

Thanku

Tommy C. Little

P.S. This is only 1 of 2 Remington
guns that I - (me and my son) own; the
other is a 700 BDL - 270 also recalled
for safety on + 0465 switch problems.