

RECEIVING AND ESTIMATING REPORT

COMMENTS

potter

ORDER
R 93-10346

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 04/19/93	DATE OPENED 04/21/93	DATE CODE KD 5-77	SERIAL NUMBER A6145826	NEW SERIAL NUMBER	MODEL AND GRADE 788 223	
ACCESSORIES L/CLIP		W/STUDS		SCOPE BASE		L/SIGHTS

FROM:

SCHULTE, BILLY
RT 5 BOX 330A
VICTORIA

TX 77901

SHIP TO:

SCHULTE, BILLY
RT 5 BOX 330A
VICTORIA

TX
77901

CUST NO: 078300 C.D.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 5-7-93	VIA UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

UP5
COD

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Rifle mfg. 1977 - purchased used, cannot duplicate customer problem, however, examination has revealed that trigger assembly has been removed from action. Rotted trigger pin safety upset.

ARTS	COMMENTS					
	Rifle trigger assembly replaced at 1/2 normal replacement cost, clean action					
	Go ahead per phone 5/12/93					
	REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS05436