

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER
R93-25254

INITIAL CUC ORDER NO.

FES

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/16/93	11/22/93	DZ 9-75	6899213		700 30-06 BDL

ACCESSORIES W/STUDS HARD CASE

FROM:

SMITH, RICHARD
C/O ROGER BEASLEY VOLVO
6375 HWY 290 E.
AUSTIN TX 78723

SHIP TO:

SMITH, RICHARD
C/O ROGER BEASLEY VOLVO
6375 HWY 290 E.
AUSTIN TX 78723

CUST NO: 087656 C.B.D

ACCOUNT NUMBER

ACCOUNT NUMBER/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

12-10-93

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, unable to disassemble. Customer concerned. However, examination revealed that action and trigger assembly are slipping and coming with heavy sticky substance. Ball stop where working sluggish. Safety words hard, more than normal force required at times.

COMMENTS

Before complete trigger assembly & then action in position of good work.
Examined the above with Mr. Smith via phone 12/13/93

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
RBS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

PS05466