

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-32327

INITIAL	CUSTOMER ORDER NO				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/07/94	11/10/94	OS 7-69	6257352		700 308 WIN ADL
ACCESSORIES		4/STUDS			

L/FRONT SIGHT

FROM:

SHIP TO:

LANE, STEVEN
BOX 63A
TURIN

NY 13473

LANE, STEVEN
BOX 63A
TURINNY
13473

CUST NO:063618 C-D.DL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM DATE	ESTIMATED	VIA
		☐			V08051

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		R1				
TRIGGER GROUP		R2			F1	F1
BOLT ASSY		R3			F2	F2
BARREL ASSY		R4		D1	F3	F3
REC ASSY.		R5		D2	F4	F4
WOOD		C1		D3	F5	F5
METAL		C2				

MAIN FAULT

Left trigger 1969, upon report to right and in operation, the trigger will not retract or pull to right end. Examination revealed that 3 trigger adjustment screws loose to R-1st. This is no longer adjustable.

PARTS

COMMENTS

26345

Replaced the complete trigger assembly and when reset at 1/2 normal adjustment, as a given it goes well.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PAT
WST					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV