

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-15158

INITIAL CUSTOMER ORDER NO.

FDC

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/05/94

05/06/94

KZ 5/75

6860013

700

270WIN.

BDL LH

ACCESSORIES

W/STUDS

FROM

SHIP TO:

SUTTON, JOHN M.
3019 MOJAVE
LAS VEGAS

NV 89121

SUTTON, JOHN M.
3019 MOJAVE
LAS VEGAS

NV
89121

CUST NO: 097011 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Reloading 1925 Upon receipt, we were unable to duplicate customer concern. Examination revealed that the powder was not over time down here from re-set and re-loaded.

PARTS

COMMENTS

#26345 Trigger Assembly

Trigger pull measured 3 3/4 to 4 lbs as recd. was 4 lbs .009

Replace complete trigger assembly and clean action at 1/2 normal replacement trigger cost, as given of good work

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/94

to A/S 5/19/94

PS05665