
P. 02



Robert Haskin Remington Arms Company Inc Delle Donne Corporate Center 1011 Centre Road, Room 218 Willimington, DE 19805-1270 November 28th, 1994

Dear Mr Haskin:

On November 26th 1994, I and my wife Debbie were returning home from our deer stands. While I and my wife Debbie was preparing to un-load our firearms Debbie's 30.06 Model 700 Bolt action discnarged while she was lifting the bolt to remove the round that was lodged in the chamber. As I stated to you during our phone conversation today this was not the first time this firearm has discharged during un-loading.

This firearm was a gift from my father-in-law Robert Beck. Mr Beck purchased this firearm new. After the first mishap Mr Beck took the Model 700 to a gunsmith to have it inspected. The firearm was cleaned and returned to Mr Beck with out any type of explanation as to why this firearm had discharged and almost causing grave injury to his son Robert Beck Jr.

I am happy to say that know one was hurt because of this integration discharge but I am sorry to say that our home has received so damages because of the firearm discharging. The bullet went through the wall of our home creating a large hole as well as going through our new sofa sleeper and than passing through our pump house. I hope that Remington Firearms would be willing to compensate us for these damages as well as repairing the Model 700 Remington 30.06 to prevent this from happening again.

So in closing let me say that I appreciate your concern you falt during our phone conversation in regards to this matter concerning the Model 700. I will wait for your response to this letter and the enclosed statements concerning the damages to my home and property. I am very confident that we can resolve this issue soon. I ship the Model 700 out to you as soon as we hear back from you.

Sincerely, Winn

Jack Swomfger Ur ~880t F. Bebe Road Solon Springs, WI 54873. (715-375-2212)

Copy, Steve Zuber/atty/1215 Belknap St/Superior W. File\WP6.0\C:\firearm