

## RECEIVING AND ESTIMATING REPORT

COMMENTS

*Add to Setup file*

ORDER

R 24-13002

*OK 4/20/94*

INITIAL CUSTOMER ORDER NO

FPS

CALL TAG ATTN: JACK KAST  
W/SEE THRU SCOPE MNTS.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/14/94

04/11/94

DI 7-76

A6331331

700

30-06

ADL

ACCESSORIES

SLING STRAP

W/STUDS

W/SWIVELS

FROM:

SCREEN, TIM  
2233 FIERO ST.  
BATON ROUGE

LA 70808

SHIP TO:

SCREEN, TIM  
2233 FIERO ST.  
BATON ROUGELA  
70808

CUST NO: 095971 C-10.1

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC ASSY.

WOOD

METAL

MAIN FAULT

The weapon discharged when the safety lever was moved from the safe position to the fire position and safety lever must be moved to unload gun

Mfg 7/76 unable to duplicate customer concern, trigger functioned normally in every respect. Assy. was dry and clean. Replace trigger assy. at N/C as a gesture of good will and to restore customer confidence in rifle.

PARTS

TRIG. ASSY. New Style

COMMENTS

Change to new style safety per phone call 4/20/94  
5 ear lift measured .014 as rec'd  
Trigger pull was 5 to 5 1/2 LBS

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

HB

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/94

PS05740