

RECEIVING AND ESTIMATING REPORT

COMMENTS

R 94-12159

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/06/94

04/07/94

DV 9-79

A6817421

700

7MM EXP

ADL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM

SHIP TO:

SHAHER, ARTHUR R.
5710 WEST "A" ST.
WEST LINN

OR 97068

SHAHER, ARTHUR R.
5710 WEST "A" ST.
WEST LINN

OR 97068

CUST NO. 095494 GLO.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00

8.00

28.00

Product Service

*CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT:

When 9-79 Unable to duplicate customer concern as noted. Trigger pull and overtravel screws have been adjusted outside of the factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at a special price as a gesture of good will.

PARTS

COMMENTS

Trigger pull measured 2 1/2 to 2 3/4 lbs. as noted. rear left was .013

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/94

ti A/S
5/24/94

PS05775