

2/26/91

TO: REMINGTON ARMS CO. 111C
ARMS SERVICE DIVISION
ILLION, NEW YORK 13357

^{BOLT}
CONTENTS: 1 BARRELED ACTION
REM MODEL 700
CALIBER: 30-06 SPRINGFIELD
SERIAL NO. 370141

I AM THE ORIGINAL OWNER, IF THERE
ARE ANY CALL BACKS, WARRANTIES,
OR DEFECTS THAT I WAS NOT AWARE
OF PLEASE LET ME KNOW.

SYMPTOMS: (1) TRIGGER AND SAFETY MAY
BE DEFECTIVE
(2) GUN FIRED ONCE WHEN
SAFETY RELEASED
(3) GUN SOMETIMES FIRES
2 TO 3 SECONDS AFTER
TRIGGER IS PULLED. FIRES
WHEN IT WANTS.

PLEASE ADVISE ME OF WHAT MAY
BE NEEDED AS IN THE WAY OF
PARTS AND WORK. AND IF NEEDED
AN ESTIMATE OF THE COST OF
REPAIRS.

THANK YOU,

JEFF SHAW

2329 DYNE DRIVE

% SHAW BROS ROOFING CO.

AVELON N.J. 08202

(609) 967-7766