

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 92-16123

INITIAL CUSTOMER ORDER NO

W/FLOOR PLATE, MAG BOX, MAG SPG, FOLLOWER, SCREWS

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

07/31/92

08/11/92

LK 2-90

C6504792

700 270

ACCESSORIES

L/WOOD

L/SIGHTS

FROM:

SHIP TO:

SPORTSMAN INC, THE
C/O NBS
1511 HWY 1 S
GREENVILLE

MS 38701

SPORTSMAN INC, THE
C/O NBS
1511 HWY 1 S
GREENVILLE

MS
38701

CUST NO: 007822 WILM

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

IN CONDITION

NEW
LIGHTLY WORN
WORN
VERY WORN
UNREPAIRABLE
MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

TRIGGER GROUP

B2

TRIGGER ASSY.

B3

REL ASSY.

B4

C. ASSY.

B5

DOD

C1

D3

ETAL

C2

N FAULT

Cannot duplicate complaint - rifle, trigger assembly and safety operate properly in every aspect. Rifle cannot be made to malfunction in any way.

Trigger pull 5 1/2 pounds; rear lift .011"

ITS

COMMENTS

Offer to return rifle as-is or to replace trigger assembly at \$ normal cost, as gesture of good-will, if that will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/92

PS05898