

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-10817

INITIAL FPS CUSTOMER ORDER NO. ATTN: JIM STEKL

DATE RECEIVED 04/16/92 DATE OPENED 04/27/92 DATE CODE PT 6-70 SERIAL NUMBER 6347446 NEW SERIAL NUMBER MODEL AND GRADE 700 6MM REM ADL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:

SKUTTLE MFG CO
ATTN: MARTY HANSELL
RT 10
MARIETTA OH 45750

SHIP TO:

SKUTTLE MFG CO
ATTN: MARTY HANSELL
RT 10
MARIETTA OH 45750

CUST NO: 061294 C.O.D

ACCOUNT NUMBER ACCOUNT NUMBER N/C

WRITE ☐ CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐
- NEW
-
- ☐
- LIGHTLY WORN
-
- ☐
- WORN
-
- ☐
- VERY WORN
-
- ☐
- UNREPAIRABLE
-
- ☐
- MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN AMMO FUNCTION FINISH ACCURACY FIT INSPECT

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *"The rifle has been discharging upon bolt closure"*
"The trigger pin will sometimes follow down when operating bolt manually - trigger assembly has been adjusted out of factory - trigger pull measured at 24 pounds (well below spec of 35) - trigger activation is not positive, due to this light pull."

PARTS

COMMENTS *"Offer to re-adjust present trigger assembly or, to replace trigger assembly at a normal cost, as a gesture of good-will, if it will better restore confidence in the rifle."*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92

PS05924