

File Number:	13146		Arms Service number:	
Last Name:	TITTLE		First Name:	JOHN
Street:	1510 CHURCH LANE		City:	READING
State:	PA	Zip:	19606	Home Ph:
Work Ph:		Product Type:	F	F A T
Type Concern:	PD	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING			
Cause Code:	4013	Cause:	BROKEN PARTS OR MISSING PARTS	
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND	
Settlement Detail:	PAY REPAIR COSTS ON TRUCK		Settlement Amount:	\$696.09
Date Opened Rem:		Date Opened by P/S:	7/20/00	Caliber:
Date of Incident:		Date Closed:	8/7/00	Bullet Weight:
Date to Analysis:		Date from Analysis:		Manufacturer:
Model:	40XB	Serial:		Date Mfgd:
RAMAC:	40XB	Litigation:	☐	PreLitigation:
Custody:		Obsolete:	☐	
Comments:	Gun repaired by the custom shop - broken connector - Shooter accidentally shot his pickup truck - \$696.09 in damages - We agreed to pay for truck repairs, APV issued 8/7/00			
Time of Modification:	2:42:17 PM		Date of Modification:	8/7/00