

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
ServiceORDER
R 94-32361

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 11/09/94	DATE OPENED 11/10/94	DATE CODE BA 1-80	SERIAL NUMBER B6061166	NEW SERIAL NUMBER	MODEL AND GRADE 788 243	
ACCESSORIES W/STUDS		SCOPE BASE L/CLIP				

FROM:

THOMPSON, ROSEMARY
RT 1 BOX 266T
BROWNWOOD

TX 76801

SHIP TO:

THOMPSON, ROSEMARY
RT 1 BOX 266T
BROWNWOODTX
76801

CUST NO: 107779 C.O.D.L

ACCOUNT NUMBER 063123	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 11-17-98	VIA UPS
GUN CONDITION ☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED		REPAIR CHARGE 20.00 EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 28.00		

to include
driver & labor

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	R1					
TRIGGER GROUP	D2			E1	F1	
BOLT ASSY.	B3			D1	E3	F3
BARREL ASSY.	B4			D2	E4	F4
REC. ASSY.	B5			D3	E5	F5
WOOD		C1				
METAL		C2				

MAIN FAULT

Left Mag. 1980, upon receipt we could not determine the specific
Concern. However, examination revealed that the action, trigger assembly
and firing pin assembly are needed. Two pieces of the rifle have been
properly maintained.

COMMENTS

Repair the complete trigger assembly
Clean action and firing pin assembly. as
1/2 normal repair cost. in a gesture of
good will. J. J. Adams

REPAIRMAN R. J. Adams	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS06034