

November 2, 1994

Remington Arms Company, Incorporated
Arms Services Division
14 Haepler Avenue
Elion, N.Y. 13357
Attention: Ed

We spoke a couple of times on the telephone in August of this year about a firearm I own. Family illness has prevented me from following up until now.

Rifle is a 988 model 243 Remington bolt action. I hunted last year and the first day it was fine. Next day each time I injected a shell into the chamber it would fire. Thank heavens I was in a stand (box) and could point it nowhere but upwards. After the 5th shell exploded I stopped trying and quit hunting. Please let me know if there will be much repair involved.

915-784-5671

Sincerely,

Rosemary Thompson
Rt. 1, Box 266T
Brownwood, TX 76801

OFFICE COPY

RDONE 11/14/94