

# RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Series

ORDER  
# 95-04314

INITIAL  
JJM

CUSTOMER ORDER NO

W/FLOOR PLATE, MAG BOX, MAG SPG, FOLLOWER, SCREWS

DATE RECEIVED  
01/20/95

DATE OPENED  
02/03/95

DATE CODE  
AQ 3-78

SERIAL NUMBER  
A574297

NEW SERIAL NUMBER

MODEL AND GRADE  
600 308

MOHAWK

ACCESSORIES

L7 WOOD

SCOPE BASE

L7 SIGHTS

FROM:

THOMAS, WILLIAM R  
222 FIVE POINT DR  
TALBOTT

TN 37877

SHIP TO:

THOMAS, WILLIAM R  
222 FIVE POINT DR  
TALBOTT

TN  
37877

CUST NO: 114351 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE 20.00  
EXCISE  
TAX  
INSURANCE  
UPS 8.00  
PARCEL POST  
TOTAL 28.00

*add no other  
charges*

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Rifle mfg 1978 - Upon receipt we could not duplicate the  
reported concern, however, examination revealed that the main safety  
cam, trigger housing assembly and action are covered with a heavy  
sticky substance. The main safety cam is working sluggish.  
Rifle was a good cleaning, has been properly maintained. Trigger adjustment  
seems to have been checked out.*

# 91469

COMMENTS

*Repair the complete trigger assembly  
& clean action at 1/2 the normal  
repair cost, as a gesture of good will*

REPAIRMAN REP	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

*Go ahead*

OFFICE COPY

RD6925 REV 1/84