

File Number:	21713		Arms Service number:	102613	
Last Name:	TENER		First Name:	PATRICK	
Street:	1034 SUNDOWN TRAIL		City:	SOUTH LAKE TAHOE	
State:	CA	Zip:	96150	Home Ph:	530-541-7531
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	10/26/2005	Date Opened by P/S:	10/27/2005	Caliber:	7 MM MAG
Date of Incident:		Date Closed:	10/27/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	6529190	Date Code:	AW
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
		Obsolete:	☐		
Custody:		Comments:	Could not duplicate concern. TA set screw positions altered. Replace TA \$20 under the bolt lock modification program.		
Time of Modification:	1:46:20 PM				
Date of Modification:	11/1/2005				