

5#
3/72

Remington®

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 7mm		Serial Number: 6529190	
Name: PATRICK TEUER		Date of Purchase: JULY 2001 - SALE ^{PRIVATE SALE}	
Address (no PO Boxes):			
1034 SUNDOWN TRAIL			
City: So Lake TAHOE		State: CA	Zip: 96150
Phone (Daytime): 530 541 7531		Fax: 530-54	
E-mail Address: TAHOETEUE@AOL.COM			
Please describe your problem:			
DURING A HUNTING TRIP, I LOADED THE RIFLE & CLOSED THE BOLT. DURING THE CLOSING OF THE BOLT, THE RIFLE FIRED AS THE BOLT CLOSED.			
THE WEATHER WAS 20° & SNOWING.			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
WINCHESTER AMMO - STORE PURCHASE			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <ul style="list-style-type: none"> Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. 			

could not duplicate concern
Trigger set screws altered.
Replace TPA & check over
completely, clean action
under bolt lock program
for \$20.00

Quote

Serial Number:

6529190

Model: 700



RE00102613

<http://www.remington.com/support/repairsvc/repairform.htm>