

Date: 10/27/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Patrick Tenen

R.E. Number: 102613

Reason for inspection: FBC

FIREARM

Manufacturer: Rum Model: 700

Serial Number: 6529190 Date of Manufacture: 3/72

Overall external condition: FAIR

Barrel condition: DIRTY

Receiver condition: DIRTY

Stock condition: DIRTY

Bolt/firing pin condition: DIRTY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: DIRTY

Headspace: —

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 5th

Manual safety: 0/1044

Test firing results (if applicable): —

DISPOSITION

Could not duplicate concern. Tmp. set screws
Altered. Replace TPA, check over completely, clear
Action under Bolt Lock program

ADDITIONAL COMMENTS

Don't 20.00 Quote