


Dec. 4 1989
Herndon, Pa.

Service Dept.
Rem. Arms Co.

Gentlemen,

The enclosed Rem. rifle Model 700 L.H.
Caliber 30-06 ,Serial number 6810095 is being returned
for inspection and repair if necessary of the trigger
saftey or bolt. The rifle has accidentally fired three
times for the owner. (See attached note).
The customer stated he was using Federal factory
loaded ammo.

Yours truly,
Harvey Troutman



RETURN TO :

H.A. TROUTMAN GUNS & AMMO
R.D.#1, BOX 1627
HERNDON, PA. I7830