

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-22709

INITIAL CUSTOMER ORDER NO

JJM

BOTTOM HALF OF SEE THRU MOUNTS ONLY

ATTN DENNIS SANITA

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/18/97

12/20/97

PQ 6-96

ML010045

700

50CAL

ML

ACCESSORIES

W/STUDS

FROM

SHIP TO

TATRO, TERRY
320 GOLF COURSERD
RICHFORD

VT 05476

TATRO, TERRY
320 GOLF COURSERD
RICHFORD

VT
05476

CUST NO: 149530 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

200.00

8.00

208.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

C1

C2

MAIN FAULT

Upon receipt we could not duplicate the reported concern, but did find
rust on the safety cam & trigger pin. Agreed to credit ML toward

Model 700 Mountain with change plate Commission 12/22/97.

PARTS

COMMENTS

Just the frame under scope bar. End estimate - customer will
repair in Feb. 98

Supply replacement m/700 Mountain w/ 30/06 (925859)

New #

in package

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

WIP ML after repair

OFFICE COPY

RD6925 REV 7-97

PS06133