

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R 94-35116

INITIAL IM	CUSTOMER ORDER NO.		DATE OPENED 12/07/94		DATE CODE EN 10-93	SERIAL NUMBER C6835359	NEW SERIAL NUMBER	MODEL AND GRADE 700 21-06	BDL
ACCESSORIES W/STUNGS		SCOPE BASE							

FROM:

SHIP TO:

TORIAS, JOHNNY
3129-B SHERMAN CHURCH RD
MAGNALIA MS 39652

TORIAS, JOHNNY
3129-B SHERMAN CHURCH RD
MAGNALIA MS 39652

CU I NO 109854 C.D.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM DATE 12-28	ESTIMATED 12-28	VIA UPS
GUN CONDITION ☐ NEW ☐ SLIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			REPAIR CHARGE 20. EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 28.00		

NO other charge CDD

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP						
BOLT ASSY						
BARREL ASSY						
REC ASSY						
WOOD						
METAL						
MAIN FAULT <i>Repld Mfg 1993 - Upon receipt, the rifle is inspected, the trigger pull not used, observation would be that the trigger assembly & trigger group have been re-set. Important in view of our specifications. Trigger has been removed with trigger group.</i>						
PARTS <i># 345</i>			COMMENTS <i>Repld the complete trigger assembly at 1/2 the replacement cost, in a matter of 2 days and 10 dollars</i>			

REPAIRMAN MS	PP 10F	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/9