



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00062936	Description/Serial Number D6591746	Repairman - Herb Brown Date Received - 3/17/2003
Account # - R-	Model 700 Center Fire Caliber: 7MM-08 MOUNTAIN RIFLE DM	Estimate Date - Current Date - 3/26/2003
Customer TIMOTHY ROBERTS 8132 US RT 2 PLAINFIELD. VT 05667 US		Return To TIMOTHY ROBERTS 8132 US RT 2 PLAINFIELD. VT 05667 US
Phone (H) (802)-454-7111 Phone (W)		Fax Email

Reported		Problems	Found
M990	FIRES ON OWN	M123 M239	FORWARD TO PRODUCT SERVICE F REPLACE TRIGGER ASSEMBLY

Material #		MaterialDesc	Repair		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part								
F26345		700 TRIG ASSB RH			1	1	0	N
Part Total:					1	1	0	
Service								
4000294		GR-CHECK TPA			1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING			0	0	0	N
4000119		GR-TEST			1	1	0	N
Service Total:					2	2	0	

ProblemNotes Trigger adjusting screws re-set. Replace trigger assm. 1/2 MSP.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date