

Remington.

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 895-3200

December 5, 1994

Mr. Carl S. Taylor
113 Ardith St.
St. Albans, WV 25177

Dear Mr. Taylor:

Your recent letter that was addressed to our Ilion, NY facility, regarding the difficulty you experienced while using your Model 700 270 caliber rifle, has been forwarded to this office for handling.

We were indeed sorry to hear that you were having a problem of any kind with one of our products.

Generally, the type of problem that you describe results from either improper adjustment of the trigger assembly outside of our factory, from improper maintenance of the rifle, from inadvertent contact with the trigger when the safety was in the fire position or from inadvertent contact with the trigger when pushing the safety lever from safe to the fire position.

We would be most interested in examining the rifle to try to determine the cause of the problem. We would appreciate your cooperation in sending the firearm via UPS to:

Remington Arms Co., Inc.
Attn: Jack Kast, Product Service
14 Hocfler Ave.
Ilion, NY 13357

Please boldly mark the two (2) butt ends of the box "KAST" to expedite handling. Also, include a brief letter that includes your return address, your concern and your telephone number.

Upon receipt, we will examine your rifle and report our findings to you.

For your reference, my direct phone number is 315-895-3558.

Thank you for bringing this matter to our attention.

Sincerely,


J.L. Kast
Product Service

JLK:tp

OFFICE COPY

PS06207