

5-26-95

Dear Sir

On my Speedmaster  
I have been firing your  
Tiger Shells! On two  
occasions the percussion  
end was blown off when  
firing. I have left the  
Casing in the chamber after  
the last time someone  
could see what happened.  
I now anyone I talked  
with has never heard of a  
22 doing this.

Frank

LE TUCKER  
10077 NEBEL SPRING RD  
CONCORD NH 03301

I recommend  
of brass was  
bored at N/C

and bore be  
entirely