

Remington.
REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 895-3200

April 4, 1995

Attn: Mitch Urbanski
Transpak, Inc.
6515 Cobb Drive
Sterling Hts., MI 48312

Dear Mr. Urbanski:

I have received your letter and Model 700 trigger assembly; unfortunately, I cannot simply send you a replacement, as it is a restricted item.

I noted that both the pounds pull screw and the sear engagement screw have been adjusted outside of the factory. Please note that this is not recommended.

Perhaps the simplest solution would be to take your gun to one of our New Gun Repair Stations in your area (list enclosed) with this letter for a no charge replacement. They, in turn, can attach this letter to their warranty form and return for reimbursement. The other option would be to return your gun to my attention for same work as outlined above.

Also, please find an owner's manual enclosed for your convenience.

Sincerely,

J.L. Kast
J.L. Kast
Product Service

JLK:tp
encl.

*Talked on phone 4/11 @ 8:20
He wanted to have trigger sent
Explained why it could not, offered
expedited service if he wanted to
return the rifle or warranty station
as outlined above*