

Remington Arms Co., Inc.
Product Service
Legal Case #:2605

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
149141	8/12/2008	8/13/2008	8/13/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Ace Hdwe Gun Store		Ace Hdwe Gun St	2200 Lakeside Dr	Lynchburg	VA	24501		W 434-385-6388

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on safe release Concern:1007 Fired on Safe Release			
C				

Could not duplicate concern. Upon removing the stock we noted a build up of sticky residue and dirt on the TA and under the receiver and bbl.

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	20000	6873027	PZ	6/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPT CNT MONTDALE PA		U			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Bolt Lock Modification Program						

Repair/Replacement Cost	Repair/Replacement Date
65.00	8/13/2008

Returned to AS for the bolt lock modification program fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		Supry
	Exam Date		8/13/2008
	Product Type		RF
	Action Type		A
	Assigned To		Supry
Cause	4015	Improper Maintenance	Could not duplicate but noted build up of sticky residue and dirt on the TA and under the receiver and bbl.
Barrel	Description		24 inch Model 700 300 Win Mag
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Worn; Functioning	

	Condition			
Bolt	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
Extractor	Condition	Slightly Worn; Functioning		
	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	True		
Locking	Block Condition	---Select---		
	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	---Select---		
Magazine	Condition	---Select---		
	Box Condition	Slightly Worn; Functioning		
Overall	Exterior Condition	Slightly Worn; Functioning		
	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	---Select---		
Receiver	Condition	Slightly Worn; Functioning		
	Bulged	False		
Safety	Description		Model 700 Bolt Lock	
	Function	Slightly Worn; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	---Select---	Sear movement is free	
	Notch	Slightly Worn; Functioning		
	Pull	Trigger	Condition	Slightly Worn; Functioning
---Select---			not measured	
Altered			False	
Sub-Assembly			M/700 Non-Bolt Lock	

RECEIVED
AUG 15 2008
BY: _____

#2605
149131

330356

☐ ESTIMATE
(Valid for 30 days)

DATE 8 / 4 / 08	☐ SERVICE ☐ INSTALL	☐ WILL CALL ☐ DELIVER	PHONE 540-296-1188
NAME Ace Hardware & Gun Store 2200 Lakeside Drive Lynchburg, VA 24501 434-385-6388			MAKE REMINGTON
			MODEL 700
			SERIAL 6873027

1. NATURE OF SERVICE REQUEST

QTY.	PART #	DESCRIPTION OF PARTS OR MATERIALS	PRICE	AMOUNT
		WHEN TAKEN OFF		
		SAFETY TO RAIL		
		BOLT, GUN FIRES		
		Return to AS for Bolt Lock		
		MODIFICATION PROGRAM		
		FLS 8/13/2008		
LABOR PERFORMED			TOTAL MATERIALS	
SEND TO:			TAX	
REMINGTON			TOTAL LABOR	
			TOTAL AMOUNT ▶	

Serial Number: 6873027

Model: 700



RE00149131

Serial Number: 6873027

Model: 700



RE00149131