Unknown

Remington Arms Co., Inc. Product Service Legal Case #:2460

Case Information

رسدين سسدد ـ

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

146240 6/10/2008 6/11/2008 6/11/2008

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Cimino's Gun & Archery Cimino's N306 Tree Ln Merrill WI 54452 W 715-536-1021

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern

rifle fired on its Canagary 1025 Unexplained Discharge - No Mention of Safety

own Concern: 1023 Position

C

6/13/08-correspondence from repair-dealer opened the rifle case. Without touching the bolt or trigger, the rifle fired when they picked it up. lw 6/13/08-Ed spoke to customer, rifle had been sitting in case under bed for over 10 years.lw

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/270 WIN C6306264 EI 10/13/1988

Date Purchased Where Purchased Accessories Original Owner

MATHEWS & BOUCHER TWO PIECE SCOPE BASE U

CONCERN: WENT OFF BEFORE TOUCHING BOLT

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Repair at disount

Repair/Replacement Repair/Replacement Cost Date

6/13/08-Quote sent to repair at discount.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		6/11/2008
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	SPENT CASE RETURNED
Barrel	Description		22" 270 WIN
	Date Code		EI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2460&Type=Case

6/13/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	=-
	Face	Slightly Worn; Functioning	=
	Handle	Slightly Worn; Functioning	=
	Stop	Slightly Worn; Functioning	=
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	==
	Ext/Eject Test	False	=
	Block Condition	Select	퍽
Locking	Lug Condition	Slightly Worn; Functioning	
C	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
•	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Teiggar	Pull	Select	5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

CIMINO'S **GUN & ARCHERY, INC.**

N306 TREE LANE . P.O. BOX 855 . MERRILL, WI 54452 715-536-1021 Fax 715-536-4040

All Sales Final. Lay-A-Ways Due In 90 Days. No Cash Refunds On Lay-A-Ways. No Warranty On Military Firearms. No Refunds Or Exchanges On Special Orders, Firearms, Ammo Or Scopes. 10% Stocking Fee On Cancelled Lay-A-Way Items.

If You Leave A Loaded Firearm Within The Reach Or Easy Access Of A Child, You May Be Fined Or Imprisoned Or Both If The Child Improperly Discharges, Possesses Or Exhibits The Firearm.

Customer's	31.08
	2431.08 ₂₀
Name Kenington Hem Servi	
Address ATTN. Service Opp. 14H	oefler Ave
TION 1913357 Phone: SOLD BY CASH C.O.D. CHARGE ON ACCT. MDSE. RE	
SOLD BY CASH C.O.D. CHARGE ON ACCT. MDSE. RE	TD. PAID OUT LAYAWAY
QUAN: DESCRIPTION	PRICE
Kemington 700	
270cal # C 6306000+	Ann Anterior and Anne Control and Anne C
}	
Placelookover-	
I had talk to ABAT Ed	B788
May 16.08 - CUSTOMER has	, ·
(1)	1 !
are Store I (DOD) open up the RI	
WAS going to open bolt BUT B	efore I could
touch bolk Rific Went OFF - m	y other hand was
Nowhere near tigger. Riste je	ost want off.
Is there any way or telling i	1 1
OFF ?? I am sending empty ca	I -2 I I
ANY QUESTION PLEASE LET "	
PN# 715 536-1021	
Thank you?	
All, claims, and returned goods MUST to accompanied by this, bill (TAX
Received	
Ву	TOTAL

could not duplicate over in which were the formation was a function where the province wards.

LUAN & Norman Quale

AT 1/2 Norman Quale

5306264

Minis Service : Repair (INExtimate System) File Add: Repair	<u> </u>
Repair Number RE00146240 Serial: C6306264 Model: 700 LH: Center Fire Repairment Verify Repair Caliber: 270 WIN Produced: 10/13/1988 Status: New 6/10/20096:10:27 AM:	
Address Information	
Contact / Condition Problems Estimate History // Status Shipping / Billing /);	
Date Code User ID Desc1 Desc2 Shipping Hold, New Valentds Repair Added Interface Hold 67/10/2008 5:10:27 AM From Check In To: Repair Bench Estimate Sent Repair Bench Repair Location Rassed Inspection ILIN	
Repair Search Close	
eupyn 6/11/2008 10.07AM CAES NUM INS 15EPE LA STATE A SUBDOMBURGONIA A MICOSONIA DE MARCONIA DE MARCONIA DE MARCONIA DE MARCONIA DE MARCONIA DE MARCONIA	Jakasa (Joe) mam

The rifle may have moved forward and the trigger to activated by material inside the case, we could not get the rifle to fire without polling the trigger.

FRED