

Remington Arms Co., Inc.
Product Service
Legal Case #:2093

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
141224	2/4/2008	2/25/2008	2/5/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Hyatt Coin & Gun	Hyatt coin & Gu		3332 Wilkinson Blvd	Charlotte	NC	28208		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fires when bolt closed or safety off	Cause:4038 Concern:1008	Could Not Duplicate Concern Fired on Bolt Closing	Unknown
C				

2/8/08--correspondence from repair-gun goes off when bolt is pushed down or when safety is removed.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	20000	A6461316	KO	5/1/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	FULKS SPORTING CLARKSBURG WV	TWO PIECE SCOPE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
	Repair/Replacement Cost	Repair/Replacement Date				

2/8/08--quote sent to replace TA under smp.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/25/2008
	Product Type		RF
	Action Type		A

	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		KO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY/STICKY
	Pull	---Select---	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Telephone: (704) 394-0387

Fax (704) 399-3388
www.hyattguns.com
www.hyattcoins.com

HYATT COIN and GUN SHOP, INC.

3332 Wilkinson Blvd.
Charlotte, N.C. 28208

No. L005097

Customer's
Order No.

1357

Date

1/31/2008

DL #

45

Name

REMINGTON ARMS SERVICE

PH #

DIVISION

LOS 177

Address

14 HOEFLER AVE.

PH #

22"

City

JALON

State

NY

Zip

13357

DOB

E-Mail

SOLD BY

CASH

ACCT. REC.

CHARGE

CHECK #

QUAN	DESCRIPTION	PRICE	AMOUNT
1	REMINGTON 700	243	
	# A6461316		
	SIR		
	OUR CUSTOMER COMPLAINS		
	THE GUN GOES OFF WHEN BOET		
	IS PUSHED DOWN OR WHEN		
	SAFETY IS REMOVED. PLEASE		
	CONTACT - THANKS.		
	FOR: DAVID B. BRICK		
	141224		

ALL claims and returned goods MUST be accompanied by this bill.

Received by

ALL LAYAWAYS 90 DAYS MAXIMUM. NO REFUND.

could not duplicate concern
TRIG SET screws fixed.

TRIG ASSM has a partially
direct & strictly lubrication
instructions. Replace TPA check
over clean under bolt
lock program for \$20.00 + \$4.14

Serial
Number:

A6461316

Model: **700**



RE00141224