

Remington Arms Co., Inc.
Product Service
Legal Case #:3548

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
169490	6/12/2009	6/16/2009	6/16/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		David	Murray	3106 NYS Rte 8	W. Winfield	NY	13491		H 315-855-7613

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Fired on safe release	Concern:1007	Fired on Safe Release	Unknown
C				

6/22/09-gun fired when safety placed to off.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	20000	A6253052	LI	2/1/1988
Date Purchased	Where Purchased	Accessories	Original Owner			
	GARY HYER ILION NY	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA at n/c						

Repair/Replacement Cost	Repair/Replacement Date
35	6/22/2009

6/22/09-replace TPA at n/c.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/16/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	RIFLE WAS IN FOR TRIGGER CLEAN/ADJUST BEFORE
Barrel	Description		22" 308 WIN
	Date Code		LI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn; Functioning	

	Condition		
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.015
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG AND PIN RUSTED TRIG BINDING
	Pull	---Select---	9#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Receipt Of Firearm(s) Delivered to the Plant for Repair
Firearm Checked For Live Ammunition [X]

File 700 5041

Delivery Date 6/11/09

Customer Name (Print) David Murray

Address 3106 NYS Rte 8 City W. Winfield

State N.Y. Zip 13491 Phone Number (315) 855 7613

Fireman Description Model 700 Cal./Ga. 308

Serial Number A6253052

Stock/ Fore-end Condition circle the description

(Excellent, Good, Fair, Poor, Fancy, Plain, Synthetic, Wood)

Comments on Stock/ Fore-end condition _____

Metal Condition circle the description

(Excellent, Good, Fair, Poor, Fancy, Plain Stainless Steel)

Comments on Metal condition _____

Barrel Type (VT. Rib; Plain; Deer; Stainless Steel) Barrel length _____

List additional accessories IE Scope, Sling, Gun case and description; _____

Customer request: GUN FIRED WHEN SAFETY PLACED TO OFF

Return Process Return to Clark St. Ent. ☒ Return via UPS []

By signing this receipt the person delivering the firearm understands to be the only person to receive the firearm upon completion of repairs.

Signature David Murray Date 6/11/09
person delivering firearm

Signature Ryan Elke Date 6/11/09
security officer

Signature Martin (Inlet) Date 6/11/09
arms service / CSR

TRIG. FTRIG. P10
RUSTED AND BINDING
WILL FOLLOW DOWN.
Replace TPA AT H/C.
#230145

Customer Pick Up Verification

delivered the above described firearm to the
may lawfully possess a firearm in New York State.

_____ Date 1/1/
it be the same who delivered

_____ Date 1/1/
ess returning the firearm

Second Time in
for FTRIG. work
R#53604

A6253052

Model: **700**



RE00169490

Remington.