

Remington Arms Co., Inc.
Product Service
Legal Case #:1981

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
139470	1/10/2008	1/11/2008	1/11/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	New Era Shooters Supply	New Era		1745 Grayson Tpk	Wytheville	VA	24382		W 276-228-4776

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	fires on safe release Concern:1007 Fired on Safe Release			
C				

Correspondence from repair-gun will fire when safety taken off.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	6453127	PU	6/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	KANAWHA VALLEY DUNBAR W VA		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
	Repair/Replacement Cost	Repair/Replacement Date				

Quote sent to replace TA under smp.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/11/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	TRIG ASSM VERY DIRTY/STICKY,TRIG NOT RETURNING PROPERLY SET SCREWS ALTERED
Barrel	Description		22" 3006 SPR
	Date Code		PU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	LITE CRATERING FROM LEAKING PRIMERS
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS/SCRATCHES
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: RE00139470 Serial: 6453127 Model: 700 Center Fire Caliber 3006 SPRG Produced: 06/30/1971 Repairman Status: New 1/10/2008 7:30:54 AM

Verify Repair

Address Information

Customer: NEW ERA SHOOTERS SUPPLY Received From: NEW ERA SHOOTERS SUPPLY Return To: NEW ERA SHOOTERS SUPPLY

Address 1: 1745 GRAYSON TURNPIKE Address 2: P.O. Box: City: WYTHEVILLE State: VA Zip Code: 24382 Country: US

FFL:

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	User ID	Desc1	Desc2
1/10/2008 7:03:2	valentds	Repair Added	
1/10/2008 7:29:2	valentds	From: Check In	To:
1/10/2008 7:30:5	valentds	Repair information change	
1/11/2008 9:09:1	supryfl	Returned to AS for repair	Bolt lock modification program

Shipping Hold ☐ InterFace Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair ☐

Current Status: New 1/10/2008 7:30:54 AM valentds Check In Repair Location: ILN Current Location: ILN Transfer Number:

Repair Search Refresh Close

supryfl 1/11/2008 9:09 AM CAPS NUM INS SCRL

Start Inbox - Microsoft Outlook Arms Services Repair Microsoft Excel - PSH... Command Cases - Micro...

6453127

Serial Number:

Model: 700



RE00139470

NEW ERA



SHOOTERS SUPPLY

Div.: New Era Mktg.
1745 Grayson Turnpike
Wytheville, VA 24382
276 - 228-4776

637

CUSTOMER'S ORDER NO.		PHONE		DATE	
		6498		12.15.87	
NAME <u>Edward C Eversole</u>					
ADDRESS <u>132 Brook Ln Max Meadows VA 24360</u>					
Return to: <u>Remington Arms, 14 Noellen Ave, ILION NY</u>					
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	PAID OUT
					13357
QTY	DESCRIPTION	PRICE	AMOUNT		
1	REM 700 .30-06				
	SN# 6453127				
SAFETY ISSUE!!!					
When gun is taken off safety, it will then fire without pulling the trigger!! HAS had NO modifications; ORIGINAL OWNER.					
TAX					
RECEIVED BY					TOTAL

All returned goods & claims
MUST be accompanied by this bill.

THANK YOU

pu 6/71
4#
22"
.010

Trig-Set screws altered
Trig. Assm dirty/sticky
Trig. Does not return
properly. Rip in
TPA, check over,
clean under bolt
lock program for
\$ 20.00 + S+H

Quote