، د لا

۰ ۳ <mark>.</mark>

Remington Arms Co., Inc. Product Service Legal Case #:2825

Case Infor	mation							
RE# 153862	Date Op 10/27/2		ate Opened(PS) 10/29/2008	Date C 10/29/2		dent Date	Pre Lit	Lit Obsolete
Customer	Information							
Туре	Business	First Name	Last Name	Street	City	State 7	Zip Age	Contact
Incident		James	Hoyle	1045 Hill St	Myrtle Creek	OR 97	7457	H 541-863-1996
Incident Ir	formation							
C	Claims		Codes		Repair Est	. Medical	Treatment	t Medical Status
PI								
PD		Cause	•••••			Un	known	
S fired C	on safe rele	ase Conce	rn:1007 Fired on	Safe Release		0.1		
			e cross pin was n ne apart in his ha		mer says that the	e gun fired v	when he rele	eased the safety and
Firearm In	formation							
Mfg	<u>7</u> .	Туре	Μ	Iodel/Ga.	SKU	Serial	Bbl.	DOM
Remin	-	CF/BA		0/270 WIN	85632	71430045	LC 2/25	/2008 2:27:44 AM
Date Pur	chased	Where Pure			Original Owner	•		
8/12/2		AL-MART ST		OPE BASE	Y			
CONCER	N:FSR,THE	EN BOLT CAN	AE APART					
	ducts Inform	ion - None Den nation - None I						
	-		R	emington/770/	′CF/BA			
Settlemen	t Releas	e of Claims	Release]	-	imbursement	Cash Settlement	Reim.] t APV	
	Repair/	Replacement Cost	Repair/Repla Date					
10/29/200	8 returned to	o AS for n/c re	pair under warrar	ıty fls.				
			R	emington/770/	′CF/BA			
Settlemen	t Releas	se of Claims	Release	Date Re	imbursement	Cash Settlement	Reim. 1 t APV	
	Repair/	Replacement Cost	Repair/Repl Date					
10/29/200	8 returned to	o AS for n/c re	pair under warrar	nty fls.				
Examinati	on[Remingt	ton/CF/BA]						

Part	Sub-Part	Code	Comment		
Examination	Examiner		B.TRAVIS		
	Exam Date		10/29/2008		
	Product Type		RF		
	[

- - - - - ----

_

~ ~ /

. . . .

..

.

~ ~

-- ----

·- · _ ·

-

	Action Type		Α
	Assigned To]	F.SUPRY
Cause	4014	Defective Parts	APPEARS FIRING PIN CAME OUT OF THE BOLT CROSS PIN MISSING
	Description		22" 270 WIN
	Date Code		LC
	Bore Plugged	False]
	Bulged	False]
Barrel	Fired	False]
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	BOLT RECEIVED UNASSM
	Shroud	Like new; Functioning]
Bolt	Face	Like new; Functioning]
	Handle	Like new; Functioning]
	Stop	Like new; Functioning]
	Condition	Like new; Functioning]
Extractor	Cut Condition	Like new; Functioning]
	Ext/Eject Test	False]
	Block Condition	Select]
Locking	Lug Condition	Like new; Functioning]
	Notch Condition	Select]
Magazine	Condition	Select]
Magazine	Box Condition	Like new; Functioning]
	Exterior Condition	Like new; Not Functioning	
Overall	Stock Condition	Like new; Functioning]
	Fore End Condition	Select]
Receiver	Condition	Like new; Functioning]
Receiver	Bulged	False]
	Description		STANDARD M/770 SAFETY
Safety	Function	Like new; Functioning]
	Sub-Assembly	Non-ISS]
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	N/A
	Altered	False]
	Sub-Assembly	Other Remington	

Arms Services Repair & Estimate	and other a second subject of the second	CSR Tools Reports Table Ma		ice Heb	
🕄 Repair Inquiry	and a second state of the second s				
Repail Number [RE00153862] Veilly Repair	Senal: 71430045 Model 770 C 270 WIN Produced: 02/25/200	enter Frè-Caliber Repairman 18 Status	Charles Swanso Repairing 10/29/2008.6		
Address Information Customer Name: JAMES HOYLE	• Received From	Return To JAMES HOYLE	C Receive	bd From	
Addiess 1: 1045 HILL STREET	PO Box	1045 HILL STREET	POBox		
Gity MYRTLE CREEK State: DR Zip Code: 197457	Country: US	State: DR Zp.Code 97457	Country:US		
Contect / Condition	Problems Esti	maleHistory / S	Current S	lalus	
10/23/2008.10:2 New 10/24/2008.10:2 Expedite 10/24/2008.10:3 Expedite 10/27/2008.10:3 Expedite 10/27/2008.12:3 Estimate 10/29/2008.6:41: Maint	valentds Repair Added pencerl From: Chack I pencerl From: Repair I swansonch Estimate Upda Travisbw Repair Mainte	n T'InieF Bench F Estima ate Parts	ace Hold 10/29/2008 0 ste Sent swansc Received <u>Repair Lo</u>	B1425AM binch bench boation	
10/29/2008.05 Estimate 10/29/2008.05 Estimate 10/29/2008.014 Estimate	swansonch Estimate Upd swansonch Estimate Upd	hte Γ Return	d Inspection ELA n As Received Current La een Approved Transfer I at Repair	ocalion I	
Repair Search			Refresh	<u>Close</u>	
Supril 107	29/2008	ICAES	Inte		
THE OWNER AND A DESCRIPTION OF A DESCRIP	Out: Arms Services Rep	and a set of the set o	PROPERTY AND		

Repairing under accounty s/c

¢,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	2825	22" 2/08
	Remington.	
	Factory Repair Instructions (NOTE: Please print and complete this form, and then include it with your firearm.)	
	Model Number: 770 Serial Number: 7/430045	
	Are you the original owner?:	
	Name: James Houle Date of Purchase: 8-12-08	
	Address (no PO Boxes): 1045 Hillst	
	City: Myrtle Creek State: ()ve Zip: 97457	
	Phone (Daytime): \$63-1996 Fax:	
	E-mail Address: $54l$ I would like to receive future e-mail updates from Remington.	
	Please describe your problem: I Took The Quin OUT	
	On Opening Day, and Never got	2
	To shoot it. It went OFF when	5 2 -
	I Relased the Safty. I Exceled	
	The spent shell and the Bolt	
	Came aftert In Nly hance	
·		
	Ammunition Information:	
	Manufacturer: Renin ton Type: 270 Win:	
	Other (i.e. bullet weight/type, shot size, powder): 150 Gr - Core - OKT SP.	
	Her, RJ70W4	
	Handload Information:	
	Powder Used: Powder Weight:	
	Case/Hull Used: Primer Used:	
	Bullet Type/Shot Size: Reloader Used:	
	Firearms Care (Cleaning and Lubrication): Hoppes #9 Solvent	1
	Brand of cleaning solution used:	١
	How often do you clean the bore? (Months or Number of rounds) AFTER 12 rounds How often do you clean the action? (Months or Number of rounds)	.
	How often do you clean the trigger assembly? (Months or Number of rounds) Same	
	Brand of lubricant used: HODDE'S HOLUBRICATING OIL	
		а.
		.er)
		, uer)

PS 10281

	How often do you lubricate the bore? (Months or Number of rounds) Same as a lean Das
	How often do you lubricate the action? (Months or Number of rounds)
	How often do you lubricate the trigger assembly? (Months or Number of rounds)
	Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
	comments: I Try to Kerp My gons as clean
	When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?
	What were the services performed? none it is knowe need
:	<u>(no. 01)</u>
	Ship your INSURED firearm by either UPS or Parcel Post to: REMINGTON ARMS CO., INC
	ATTN: Arms Service Divison
-15	14 Hoefler Ave
	-Ilion, NY 13357
· · ·	 FIREARM. THIS IS A VIOLATION OF FEDERAL LAW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused. Ship your INSURED firearm by either UPS or Parcel Post, Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.
	delines;
71	430045 med to you C.O.D. (To avoid C.O.D. Charges, please th your gun)
Model:	stimate detailing the nature of the repair, applicable taxes air estimate. Repairs can be paid by check, money order, i, or VISA). If you wish, you can expedite repairs over billed to your credit card.
RE	E00153862 check over completely, igh complete bolt assimt TPA Function test AT N/
	Function test AT NI
	usarpanty

and the second second

and the second second

.

and the second second

.

*