

Address Information

FFL

--	--	--	--	--	--	--

Repair Search		Refresh	Close
---------------	--	---------	-------

3390

March 28, 2009

Dear Remington,

Recently my Model 600 Remington picked up a bad habit of wanting to fire when the safety is pushed to off. I found out from your website that in 1979 there was a safety recall on these guns. Mine doesn't seem to have been repaired. Please repair it and send me the bill if there is one.

Thank you,
Anthony Coffman
1675 Cedar creek RD
Sparta, TN 38583
(931)761-2980

Serial
Number:

69499

Model: 600 MOHAWK



RE00165829

could not duplicate concern.
TPA has not been updated.
replace TPA under recall,
check over, clean at H/c

#230145

LNS/66
18.5"
5.5#
1004