

Remington Arms Co., Inc.
Product Service
Legal Case #:2727

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
152058	9/27/2008	9/29/2008	9/29/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Glick Twins	Glick Twins		419 W Business 83	Pharr	TX	78577		W 956-787-4291

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	fires on safe release Concern:1007 Fired on Safe Release			
C				

10/1/08-correspondence from repair-fires sometimes when safety is taken to off position. Customer said there had been a recall loong ago and never sent in.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/222 REM		87720	CP	4/1/1967
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	65	10/1/2008				

9/28/2008 returned to AS for Update under current procedures. We will try to find a used stock to replace the cracked stock fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/29/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18.5" 222 REM
	Date Code		CP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	RUSTY
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	---Select---	CRACKED
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/600 BOLT LOCK SAFETY
	Function	Slightly Worn; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	DIRTY
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY O/S NOT UPDATED
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00152058** Serial: 87720 Model 600 Center Fire Caliber: 222 Repairman: REM. Status: New 9/27/2008 5:50:44 AM

Verify Repair

Address Information

Customer: ☒ Received From Return To: ☒ Received From

Name: **GLICK TWINS** **GLICK TWINS**

Address 1: **419 W BUSINESS 83** **419 W BUSINESS 83**

Address 2: PO Box: PO Box:

City: **PHARR** **PHARR**

State: **TX** Zip Code: **78577** Country: **US** State: **TX** Zip Code: **78577** Country: **US**

FFL:

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	User ID	Desc1	Desc2	Current Status
9/27/2008 5:50:4	sanguinegl	Repair Added		New
9/29/2008 7:56:2	supryfl	Returned for n/c repair	As received stock is broken	9/27/2008 5:50:44 AM
				sanguinegl
				Check In
				Repair Location
				ILN
				Current Location
				ILN
				Transfer Number

☐ Shipping Hold
☐ InterFace Hold
☐ Estimate Sent
☐ Parts Received
☐ Passed Inspection
☐ Return As Received
☐ Has been Approved
☐ Internal Repair

Repair Search Refresh Close

supryfl 9/29/2008 7:56 AM ILAPS NUM INS SCRL

start Inbox - Microsoft Out... Arms Services Repair... Current Cases - Micro... Microsoft Excel - PS H 7:56 AM

Preform updates under current procedures at n/c. Try to find a used stock to replace the cracked stock.

FLS

2727



NBS
NATIONAL BROADCAST SYSTEM

1851
CP 4/67
4th
008

**OUTDOOR SPORTING GOODS
LIGHT INDUSTRIAL HARDWARE
419 W. BUS. 83 • PHARR, TX 78577**

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RETD.	PAID OUT	LAYAWAY
---------	------	--------	--------	----------	-------------	----------	---------

Serial Number:[illegible]

PS 10421